



B.M. MACCHINE UTENSILI s.r.l.

Via Edmondo De Amicis, 146 - 10093 Collegno (TO) - ITALY

Tel: (0039) 011-403.11.24 / 011-403.15.79 - Fax: (0039) 011 403.13.28

www.bmtorino.it - bm@bmtorino.it

IT 07417070013

SIEMENS

Code 5622



VARIOUS

VARIA

| Brushless Motor | Type | Tipo | Brushless Motor |
|---------------------------------|-------------|-------------|---------------------------------|
| 1FT5074-0AF01-9-Z servomotor | Accessories | Accessorios | 1FT5074-0AF01-9-Z servomotor |
| 1FT6086-1AF71-4AG1 servomotor | | | 1FT6086-1AF71-4AG1 servomotor |
| 1PH5138-4CG40-Z servomotor | | | 1PH5138-4CG40-Z servomotor |
| 1FT6062-6AF71-4AG2 servomotor | | | 1FT6062-6AF71-4AG2 servomotor |
| 1HU3056-0AFO1-Z servomotor | | | 1HU3056-0AFO1-Z servomotor |
| 1FK6063-6AF71-1EH0 servomotor | | | 1FK6063-6AF71-1EH0 servomotor |
| 1HU3074-0AC01 servomotor | | | 1HU3074-0AC01 servomotor |
| 1GG5164-0WF40-6HU7-Z servomotor | Notes | Notas | 1GG5164-0WF40-6HU7-Z servomotor |
| 1FT5072-1AC71-1AB0 servomotor | | | 1FT5072-1AC71-1AB0 servomotor |
| 1FT6034-1AK71-3EH1 servomotor | | | 1FT6034-1AK71-3EH1 servomotor |
| 1FT5064-0AF01-2 servomotor | | | 1FT5064-0AF01-2 servomotor |
| 1GL5116-0WY40-6HU7-Z servomotor | | | 1GL5116-0WY40-6HU7-Z servomotor |
| 1HU3071-0AF01-Z servomotor | | | 1HU3071-0AF01-Z servomotor |
| 1HU3076-0AC01-Z servomotor | | | 1HU3076-0AC01-Z servomotor |

The characteristics, data, measurements and photos provided here are not binding
 Características, datos, medidas y fotos no suponen compromiso ninguno